

F

30-045-23799

9-20-79

F. Loc. 990/N; 1450 Elev. 6147 GL Spd. 12-4-79 Comp. 1-15-80 TD 6198 PB 6134
 Casing S. 95/8 @ 523 W 450 Sx. Int. @ W Sx. Pr. 412 @ 6198 W 430 Sx. T. 2 3/8 @ 6012
 Csg. Perf. 6020-6056 Prod. Stim. SWF

I.P. 267 ACF 80/D MCF/D After 198 Hrs. SICIP 575 PSI After Days GOR Grav. 1st Del. 2-4-81

TOPS		NITD	X	Well Log	TEST DATA						
					Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-103	✓✓✓✓✓	Plat	XX						
Fruitland		C-104	2-21-80 ✓	Electric Log	✓✓	4-6-81	366	38	183	183	38
Pictured Cliffs	1412	5-5-81	1 1/2°	C-122	2/1/83	N	6P				
Cliff House	2320	Ditr	11-3-81	Dfa	10/14/83	N	6P				
Menefee	2400	Datr		Dac							
Point Lookout	3810										
Mancos											
Gallup											
Sanostee											
Greenhorn	5866										
Dakota	6020										
Morrison											
Entrada											

7. 11-3-81
 "11 set retained w/ 1/2" bat pipe"
 FB to Gallup
 Retainer @ 5980 w/ 59cf
 gone ahead. 2-25-85

W/320

P
 o
 i Basin Dak Co. SJ s 17 T 26N R 11W U C Oper. Merrion O&G Corp. Delhi Taylor No. 6E