UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN		OR TRIBE NAME	
	NAVAJO	5 t 5 t 5	<u> 원 김원류</u>	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGR	EEMENT NA	ME를 불일을	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)		<u> </u>	19 1 - 19 19 19 19 19 19 19 19 19 19 19 19 19	
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR	- · · · ·	= <u></u> <u></u>	
1. oil 🖂 gas 😥	DOME NAVA	JO ^c 12-26	-1 3 ዓ = -	
well well to other	9. WELL NO.		es be tidas bisys	
2. NAME OF OPERATOR	11_	# # # # E		
DOME PETROLEUM CORPORATION	10. FIELD OR	WILDCAT	MÉ a a a	
3. ADDRESS OF OPERATOR 501 Airport Drive			rured CLIFF	
Suite 107, Farmington, NM 87401	3	R., M., OR BL	K. AND SURVEY	OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA		white cult cult	
below.)	SEC. 12, 1			
AT SURFACE: 790' FSL, 790' FWL AT TOP PROD. INTERVAL:	12. COUNTY	-		
AT TOTAL DEPTH:	SAN JUAN		NEW MEXICO	
	14. API NO.	Young tal in tal it tal in	on de la	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,				
REPORT, OR OTHER DATA			DF, KDB, AND	₩D)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6069' GR	수 등 구 등 	- 등 원조이이 	
TEST WATER SHUT-OFF		ο 1 ± 2 1 ο 1 ± 2	18 - 1 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3	
FRACTURE TREAT		A 5: 3		
SHOOT OR ACIDIZE		to to Penies V torri	renta Leber Lebbrens Lebbrens Lebbrens	
REPAIR WELL			tiple completion or	zone
PULL OR ALTER CASING 🔲	change 	on Form 9-3:	30.) in the Second	⊆
MULTIPLE COMPLETE	7	9 4 5 5	- 원 관용중점	5
CHANGE ZONES	S		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2
(other) SPUD AND SET SURFACE				=
(0	<u>.</u>		<u> </u>	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	e all pertinent d	letails, and a	give pertinent da	ites
including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen	irectionally drille	ed, give subs	urrace locations	and
measured and true vertical deptils for all mainers and zeroes pertinent	,		7 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18	
	D	5 4 1 5 E	an 31joint	~
Spudded 8 3/4" hole at 12:00 noon, 12/26/79.				5
(99') 5½", 15.5#, K-55 LT&C casing. Casing la			Cemented 5	a
with 50 sacks class "B" cement with 2% CaCl.	Plug down	27.300 70 77 72		9.
Circulated cement.		tagui Sgi gi Dagh Diesin	rents, mult be ments,	
		- 2		
		oedue ulant t geawre to to any	ntting p	
) # § E E	Hans water	
		oedne has llos allon bloede e generalità to yna to carriso lo allone de los los de los llos		
		등 (J) (S (H) (S		
		di low the off the off well	ine not speka l fainter faworte fatte ali	
		is not negrous reposit reposit	17.17 18.20 19.19 19.19	
		nobna toutis 1561 (e	intua not tiongia i ispete etate i interiore state i interiore i interiore	
Subsurface Safety Valve: Manu. and Type		W is nobred. Theyou is we should be the that to that to the they are the are they are the they are the are they are the a	D = = 0 0 0 = = 0	_ Ft
18. I hereby certify that the foregoing is true and correct			4 ST 18 A TO	
SIGNED SHOULD THE DRLG & PROD FO	REMANDATE Ja	nuaxy 2,	1980= 3 = =	
H. D. HOWLINGSWORTH (This space for Federal or State offi	ice use)	oren Santa Santa Tarre	2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -	
		S. Pro	Authorities (Parallel Parallel	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE _			
		ACCEPTED	FOR RECORD	
**************************************			e de la constant de l	
21 .		be all	pod Ses Ses	
			חמיצח	

*See Instructions on Reverse Side

JAN US.80

FARISHIGTON DISTRICT