UNITED STATES DEPARTMENT OF THE INTERIOR

UNITED STATES	5. LEASE 2 5 2 3 5 5
DEPARTMENT OF THE INTERIOR	NOO_C-14-20-7476 = 355
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	NAVAJO SEEG OLAVAN
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME:
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	B. FARM OR LEASE NAME 일 신흥일
4 -4	8. FARM OR LEASE NAME 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1. oil gas	9. WELL NO. 2009 - 200
2. NAME OF OPERATOR	<u>4 5999 8 887</u>
DOME PETROLEUM CORPORATION	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 501 Airport Drive	WAW FRUITLAND PICTURED CLIFF
Suite 107, Farmington, NM 87401	11. SEC., T., R., M.; OR BLK. AND SURVEY OR AREA
 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	SEC. 13-T26N-R13W
AT SURFACE: 1120' FSL, 790'FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO. = = = = = = = = = = = = = = = = = = =
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. All plants to brack the brack to brack the brack to brack the br
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
DEGLIFOT FOR ADDOCUMENT OF DEGLIFOR AS	6068 GR 소설들로 및 급립하다 /
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	구 등을 하는 그 기계를 하는 것이 되었다.
SHOOT OR ACIDIZE	항원원 등 기를 가운 함께 다른 기를 기를 받는다.
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING MULTIPLE COMPLETE	change on Form 9-330.) The Free Property of the Property of th
CHANGE ZONES	
ABANDON*	afound naced th naced th national national at bone at bone
(other) RUN PRODUCTION CASING	Ecol building
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	
including estimated date of starting any proposed work. If well is di	irectionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertinen	it to this work.)* The second of the second
Drilled to 1328'. Ran 1317', 44 jts., 2 7/8" 6	S.5# J-55 casing=Landed
at 1317' GL. Cemented with 75 sacks 65-35 Pozm	
10# Gilsonite/sk. Followed with 50 sx. class "	
Floseal/sk, 10# gilsonite/sk. Plug down at 4:0	
cement.	Check to the M Control of the M Control of the M abandonings abandoni of the Control according to the Control
	Sale of Sale o
	그 그 그 그 그 그 그 그 그 그 이 된 수 그 이 이 도심 게 됐다.
	The first trace of the control of th
	The state of the s
	그는 그는 그를 통해 함께 함께 하는 것이 되었다.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	크리 보이 보이 보다 보다 보다 되었다.
augus . The	
SIGNED H.D. HOLLINGSWORTH TITLERLG. & PROD. F	FOREMANTE 11/13/79
(This space for Federal or State off	ice use) # # # # # # # # # # # # # # # # # # #
APPROVED BY TITLE	DATE TO THE TOTAL PARTY OF THE
CONDITIONS OF APPROVAL, IF ANY:	2555 = 45 75 5
NMOCC	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그