

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
DOME PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR 501 Airport Drive
Suite 107, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 810' FNL, 905' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

5. LEASE
NOO-C-14-20-7480

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
NAVAJO

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
DOME NAVAJO 24-26-43

9. WELL NO.
4

10. FIELD OR WILDCAT NAME
WAW FRUITLAND-PICTURED CLIFF

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA
SEC. 24, T26N, R13W

12. COUNTY OR PARISH 13. STATE
SAN JUAN NEW MEXICO

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6041 GR

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <u>SPUD AND SET SURFACE</u>	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 8 3/4" hole at 4:00 PM, 11/27/79. Drilled to 108' Ran 3 jets (100')
5 1/2", 15.5#, K-55 LT&C casing. Casing landed at 102' GL. Cemented with
35 sacks class "B" cement with 2% CaCl. Plug down at 8:45 PM, 11/27/79
Circulated cement.

RECEIVED
NOV 28 1979
GEOLOGICAL SURVEY
FARMINGTON, N.M. 87401

DEC 9 1979
GEOLOGICAL SURVEY
FARMINGTON, N.M. 87401

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED H. D. Hollingsworth TITLE DRLG & PROD FOREMAN DATE November 28, 1979
H. D. HOLLINGSWORTH

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

NMOCC