Form 9–331	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 10757
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas X other	Irish
well well other  2. NAME OF OPERATOR	9. WELL NO.
Dugan Production Corp.	10. FIELD OR WILDCAT NAME WAW Fruitland PC
3. ADDRESS OF OPERATOR Box 208, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) 790' FSL - 790' FEL	Sec 12 T26N R13W
AT SURFACE:	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA  REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6018' GR
TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  PULL OR ALTER CASING  MULTIPLE COMPLETE  CHANGE ZONES  ABANDON*  (other)	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen  Ran 42 jts 2-7/8" OD 6.5# J55 8R EUE tbg for set @ 1275' GL. Pipe was hydrotested to 400 Preflushed hole w/5 bbls wtr. Cemented w/75 w/1/4# cello flake per sx followed by 50 sx 1/4# cello flake per sx. Total slurry 214 c after dropping plug. Bumped plug w/1500 psi Shut in. POB 12:30 p.m. 12-6-79.	csg. TE 1276.23'  o psi - OK. sx 2% lodense class "B" neat w/
Subsurface Safety Valve: Manu. and Type	
SIGNED THE Petro. Eng.	DATE12-10-79
(This space for Federal or State office	ce use)
APPROVED BY TITLE	DATE
CONDITIONS OF AFEROVAL, IT ANT.	•