PULL OR ALTER CASING

Surface RecTamation

MULTIPLE COMPLETE CHANGE ZONES

ABANDON*

(other)

change on Form 9-330.)


UNITED STATES

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NOU-C-14-20-5390 6. IF INDIAM, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil gas well other Dry Hole	Dome Navajo 18-26-11 9. WELL NO.
2. NAME OF OPERATOR DOME PETROLEUM CORP.	1 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 3600 Southside River Rd., Farmington, NM 87401	Wildcat 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1030' FNL, 990' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Sec. 18, T26N, R11W 12. COUNTY OR PARISH 13. STATE San Juan New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6041' GR
REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF:	82(NOTE: Report results of multiple completion or zone

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The surface reclamation on the above location has been completed and is ready for inspection. The pits have been backfilled, location cleaned up, contoured to conform to surrounding terrain, reseeded in compliance with BLM stipulations.

FARMINGTON, N. M.



SEP 03 1982

*See Instructions on Reverse Side

NMOCC"

