UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 11775
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT WANTE
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
reservoir. Use Form 9-351-C for such proposation	Ross Federal 4-26-13
1. oil gas X other	9. WELL NO
2. NAME OF OPERATOR	2
DOME PETROLEUM CORP.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 501 Airport Drive,	WAW Fruitland Pictured Cliff
Suit 107. Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec. 4, T26N, R13W
AT SURFACE: 1520' FSL, 1520' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO. 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
CURCOUNT REPORT OF	6223 GR-
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF U U FRACTURE TREAT U	그 그 그 그 그를 들었다. 그 사람이 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING 🔲	change on Form 9-330.)
MULTIPLE COMPLETE	
CHANGE ZONES	
ABANDON*  (other) Spud & Set Surface	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	mirecilonany dimed. give substitute locations and
	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
Spudded 124" hole at 5:45 p.m., 05/12/80. Dril	led to 110'. Ran 106' (3 jts.)
o riou has wer concoracing Casing landed at	Ing. CF. Cemented with 100 2v.
class "B" cement with 2% CaCl. Plug down at 2:15	p.m. 5/13/80. Circulated cement.
RECEIVED  MAY 1 6 1980  CONTROL SURVEY	自営第5章 一見り至り蓋引
CDECEIVE 1	그는 그는 그는 그 불성학교교 그 한 음취학생 그는
1 1367	
/ WEX 7 P 1922	
U. S. GEOLOGICAL SURVEY	
U. S. GEOLOGICAL SO. M. FARMINGTON, N. M.	1 = 1 = 5
U. S. FARMINGTON,	MAY 2 0 1980: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	ကြောက်သည်။ မြို့ခွေနေရာက် မိုးလည်းမှုမှာ မေ
	VOIL COM. COM#877 PET \$#\$\$
Subsurface Safety Valve: Manu. and Type	DIST. 3 Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
	oremandate May 14, 1980
(This space for Federal or State office use)	
	-ACCEPTED FOR RECORD
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	
= = · · ·	

\*See Instructions on Reverse Side

