5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

DEFARTMENT OF THE INTERIOR	<u>NOO-C-14-20-74</u> 80
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	Navajo 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil gas well other	Dome Navajo 24-26-13 9. WELL NO.
2. NAME OF OPERATOR	#4 1 4 y
Dome Petroleum Corp.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	WAW Fruitland-Pictured Cliff
501 Airport Drive, Suite 107, Farmington, NM 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	Sec. 24, T26N, R13W
AT SURFACE: 990' FNL, 1520' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	San Juan New Mexico 14. API NO
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6036' GR
RACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* Sother) Spud & Set Surface Casing	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent	rectionally drilled give subsurface locations and
Drilled to 102'. Ran 3 jts. (96') 8 5/8", 23# landed at 98' G.L. Cemented with 100sx. Class Plug down at 3:00 p.m. 6/17/80. Circulated ce	"B" Cement, with 2% CaCl.
AGGEPTED FOR RESORD	
JUN 27 1980	
BY LIMBOUR AND A STATE OF THE S	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	<u> </u>
SIGNED H. D. H. J. ANDRES TITLE Drlg.&Prod.ForemanDATE 6/18/80	
(This space for Federal or State office use)	

____ DATE ___