

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR  
Supron Energy Corp. % John H. Hill, et al

3. ADDRESS OF OPERATOR Suite 020, Kysar Building  
300 W. Arrington, Farmington, New Mexico 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1830' FSL & 830' FEL (NW SE)

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:


16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☒  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐



5. LEASE  
SF - 078430

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
N/A

7. UNIT AGREEMENT NAME  
N/A

8. FARM OR LEASE NAME  
Newsom "A"

9. WELL NO.  
24

10. FIELD OR WILDCAT NAME  
Ballard Pictured Cliffs


11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 4 T26N R8W

12. COUNTY OR PARISH San Juan 13. STATE  
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6886' GR

NOTE: Report results of multiple completion or zone change on Form 9-330.



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Frac'd the Pictured Cliffs perforations (2826' - 2858') with 12,516 gallons 70% Quality Westfoam, 2% KCL water, 40,000# 10/20 Sand and 401,500 SCF Nitrogen.
2. Maximum Treating Pressure 2900 PSI, Minimum Treating Pressure 2100 PSI, Average Treating Pressure 2700 PSI, ISDP 1900 PSI, Final Shut-In Pressure 1800 PSI in 15 minutes. Job completed at 8:38 A.M., 4/27/81.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED James V. Wells TITLE Exploration/Development Superintendent DATE April 30, 1981

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

NMOCC

MAY 05 1981

FARMINGTON DISTRICT