PULL OR ALTER CASING MULTIPLE COMPLETE

CHANGE ZONES

ABANDON* (other)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF - 078432
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME N/A
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas well other	Hodges
Well — Well Other	9. WELL NO.
2. NAME OF OPERATOR	#17
Supron Energy Corp. c/o John H. Hill, et al.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Kysar Building, Suite 020	Ballard Pictured Cliffs
300 W. Arrington, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Sec. 21 T26N R8W
AT SURFACE: 1420' FSL & 1030 FEL (NE SE)	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	Comment of the Commen
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF KDB AND WD)
	6521' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	EIVED / OUT & Pron
SHOOT OR ACIDIZE	=IVLD Office.
REPAIR WELL	(NOTE) Report results of multiple completion of zone
PULL OR ALTER CASING OCT	2, 5 Change on North 9-330 Ch

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

U. S. GEOLOGICAL SURVEY

FARMINGTON, N. I.

1. Spudded 10 3/4" hole, to 260' at 5:30 P.M., 7/5/80, cement circulated.

- Ran 8 joints (223.7') of used 7", 26# ST&C, K-55 casing.
- Set and cemented at 223.7'.
- Cemented with 100 sacks, Class B, 3% Calcium Chloride, 1 sack flo-cele.
- Plug down at 12:48 A.M., 7/19/80.
- Circulation good. Circulated 5 bbls. of cement.
- Check water shut-off at 600# with 10", 900 Series Gardner-Denver Blow-out Preventer.

Subsurface Safety Valve: Manu. and Type		Set @	Ft.	
18. Lhereby certify that the for SUMMED WITH I	pregoing is true and correct Exploration a	nd Development dent DATE	OCT 1 6 1980	
	(This space for Federal or St.	ate office use)		
APPROVED BYCONDITIONS OF APPROVAL, IF		DATE		