Denny & But DEPUTY ON & GAS INSPECTION

DEC 2 9 1997

Maral

\$

Meter Number:93827
Location Name:HODGES 15E
Location:TN-26 RG-08
SC-27 UL-J
2 - Federal
NMOCD Zone:OUTSIDE
Hazard Ranking Score:00

DECEIVE N APR 1 4 1997 OUL COM. DIV.

# RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone 10<sup>-9</sup> to 10<sup>-13</sup> cm/sec Shale 10<sup>-12</sup> to 10<sup>-16</sup> cm/sec Clay 10<sup>-12</sup> to 10<sup>-15</sup> cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



# FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 93-827Location: Hodges 15 E  Operator #: 0109 Operator Name: Robert Click P/L District: Ballard  Coordinates: Letter: J Section 27 Township: 26 Range: 8  Or Latitude Longitude  Pit Type: Dehydrator Location Drip: X Line Drip: Other:  Site Assessment Date: 7/28/94 Area: 07 Run: 92						
SITE ASSESSMENT	NMOCD Zone:  (From NMOCD  Maps)  Inside  Outside  (2)  Depth to Groundwater  Less Than 50 Feet (20 points)  Offet to 99 Ft (10 points)  Wellhead Protection Area:  Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source?  Horizontal Distance to Surface Water Body  Less Than 200 Ft (20 points)  (3)  Horizontal Distance to Surface Water Body  Less Than 200 Ft (10 points)  (3)  Name of Surface Water Body  (5)  Greater Than 1000 Ft (0 points)  (6)  (8)  (9)  (9)  (1)  (1)  (1)  (1)  (1)  (2)  (1)  (2)  (3)  (5)  (5)  (5)  (5)  (5)  (6)  (6)  (7)  (7)  (7)  (7)  (8)  (8)  (8)  (9)  (9)  (9)  (1)  (1)  (1)  (1)  (1						
Ω	TOTAL HAZARD RANKING SCORE: POINTS						
REMARKS	Remarks: Redline Book-Outside Vulnerable Zone Tope-Outside Three pits onsite, location drippit is dry, will close one pit.						
2	PUSH IN						

\_ 1

NC	ORIGINAL PIT LOCATION  Original Pit: a) Degrees from North <u>220°</u> Footage from Wellhead <u>104'</u> b) Length: <u>24'</u> Width: <u>24'</u> Depth: <u>3'</u>
ORIGINAL PIT LOCATION	Zy' Zy'
REMARKS	Remarks: Pictures @ 1251 (16-19, Roll)  Dump Truck  No location sign, Meter not in operation.
	Completed By:
	Signature Date

/007:000\ 0. /07 /n.

## Fi\_D PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 93-827 Location: Hodges 15 E  Coordinates: Letter: J Section 27 Township: 26 Range: 8  Or Latitude Longitude  Date Started: 10-10-94 Run: 07 99 0/12/94 FM								
FIELD OBSERVATIONS									
CLOSURE	Remediation Method:  Excavation								
REMARKS	Pit Closure Date: 10-10-94 Pit Closed By: BEZ  Remarks: L'Sandsfone								
	Signature of Specialist: Vale Wilson								



### FIELD SERVICES LABORATORY ANALYTICAL REPORT

# PIT CLOSURE PROJECT - Soil Samples Outside the GWV Zone

	Field I	ID		Lab ID			
SAMPLE NUMBER:	yw 393	946375					
MTR CODE   SITE NAME:	93827	N/A					
SAMPLE DATE   TIME (Hrs):	10-10-9	1310					
SAMPLED BY:		/A					
DATE OF TPH EXT.   ANAL.:	16-13-						
DATE OF BTEX EXT.   ANAL.:	NIA	NIA		NA			
TYPE   DESCRIPTION:	γe	Light Frey Sand					
	F	RESULTS					
PARAMETER	RESULT	UNITS	QUALIFIERS			N/(1)	
			DF	Q	M(g)	V(mi)	
TPH (418.1)	1240	MG/KG		<u> </u>	12.0	28	
HEADSPACE PID	197	РРМ					
PERCENT SOLIDS	95.1	%					
			d 418.1				
		TPH is by EPA Metho					
arrative:		TPH is by EPA Metho					

\* Test Method for Oil and Grease and Petroleum Hydrocarbons \* in Water and Soil Perkin-Elmer Model 1600 FT-IR Analysis Report \*

74/10/13 11:56

Sample identification 946375

Initial mass of sample, g 2,000

Volume of sample after extraction, ml 38,000

Setroleum hydrocarbons, ppm Wet absorbance of hydrocarbons (2930 cm-1) 1.162

