5. LEASE

## UNITED STATES

DEPARTMENT OF THE INTERIOR		SF - 078384
GEOLOGICAL SI	JRVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
SUNDRY NOTICES AND RE (Do not use this form for proposals to drill or to reservoir. Use Form 9-331-C for such proposals.)	deepen or plug back to a different	7. UNIT AGREEMENT NAME N/A 8. FARM OR LEASE NAME
1. oil gas X other		Newsom "B"  9. WELL NO.
2. NAME OF OPERATOR		#20
Supron Energy Corp. c/o Joh 3. ADDRESS OF OPERATOR Kysar E	Building, Suite 020	10. FIELD OR WILDCAT NAME Blanco Mesa Verde
300 W. Arrington, Farmington 4. LOCATION OF WELL (REPORT LOCATION)	On, New Mex1co 8/401 FION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Sec. 5 T26N R8W
below.) AT SURFACE: 1850' FSL & 79 AT TOP PROD. INTERVAL:	90' FWL (NW SW)	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:		San Juan New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO IND REPORT, OR OTHER DATA	ICATE NATURE OF NOTICE,	15. ELEVATIONS (SHOW DF, KDB, AND WD 6194' GR
TEST WATER SHUT-OFF	U. C. COLOGO U. C.	(NOTE: Report results of multiple completion or zon chapge on Form 9–330.)
1. Spudded 12½" hole, to 3	317' at 5:45 A.M., 10	0/24/80. Cement circulated.
2. Ran 7 joints (307') of 3. Set and cemented at 307		b.
<ul><li>4. Cemented with 250 sacks</li><li>3 sacks flo-cele.</li><li>5. Plug down at 9:00 AM.,</li><li>6. Circulation good through</li></ul>	s Class "B" cement, 8 10/25/80. phout job. Circulate	
Subsurface Safety Valve: Manu. and Type		Set @ F
18. I hereby certify that the foregoing is tr	ue and correct -Exploration and Dev -TITLE Superintenden	velopment OCT 2 8 1990)
	(This space for Federal or State of	ffice use)
APPROVED BY	TITLE	DATE