

F

30-045-24515

8-22-80

1850/S;790/E

5951 GL

F. Loc. _____ Elev. _____ Spd. 8-29-80 Comp. _____ TD 1227 PB 143Casing S. 7 @ _____ W 50 Sx. Int. _____ @ _____ W _____ Sx. Pr. 4 1/2 @ _____ W 125 Sx. T. _____ @ _____
Csg. Perf. _____ Prod. Stim. _____1700-1230T
R
A
N
S

I.P. _____ BO/D _____ MCF/D After _____ Hrs. _____ SICP _____ PSI After _____ Days GOR _____ Grav. _____ 1st Del. _____

TOPS		NI TD	X	Well Log	TEST DATA						
Kirtland	<u>200</u>	C-103	☒	Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	<u>999</u>	C-104		Electric Log							
Pictured Cliffs			<u>1 1/2</u>	C-122							
Cliff House		Ditr		Dfa							
Menefee		Datr		Dac							
Point Lookout											
Mancos											
Gallup											
Sanostee											
Greenhorn											
Dakota											
Morrison											
Entrada											
		<u>Approved by</u>									

P
o
o
I

WC PC

Co-SJ 5 3 T 26N R 12W U I Oper. Merrion O&G Corp.

Lse. Hickman

No. 8