

Form 9-331  
Dec. 1973UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other ☐ Dry Hole2. NAME OF OPERATOR  
Jerome P. McHugh3. ADDRESS OF OPERATOR  
Box 208, Farmington, NM 874014. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1830' FNL - 1070' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☒

Request for inspection

5. LEASE  
N00-C-14-20-43246. IF INDIAN, ALLOTTEE OR TRIBE NAME  
Navajo Allotted

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Chaco Plant9. WELL NO.  
#17R10. FIELD OR WILDCAT NAME *S. Gallegos*  
~~W~~ Fruitland PC11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec 14 T26N R12W12. COUNTY OR PARISH  
San Juan13. STATE  
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6133' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

SEP 1 1984

BUREAU OF LAND MANAGEMENT  
FARMINGTON REGIONAL AREA

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The #17R Chaco Plant was plugged and abandoned on 9-10-84 as per BLM stipulations reported on Sundry Notice dated November 25, 1981. The surface rehabilitation requirements necessary for permanent abandonment have been accomplished as required by BLM conditions of approval letter dated 11-25-81. The location is now ready for BLM inspection.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

18. I hereby certify that foregoing is true and correct

SIGNED Sherman E. DuganTITLE Geologist

DATE

-9-12-84

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.  
Liability under bond is retained until  
restoration is completed.

RECEIVED

JAN 22 1985

OIL CON. DIV.

Set @ DIST. 3 Ft.

APPROVED  
AS AMENDED

DEC 18 1984

M. MILLENBACH  
AREA MANAGER