## MERRION & BAYLESS

Chaco Ltd. #3 Section 12, T26N, R13W San Juan County, New Mexico

## SLOPE TESTS

Depth	Hole Deviation
820 ft.	-0-
1300 ft.	•5 <sup>0</sup>



State	of	New	${\tt Mexico}$	)	
				)	SS
County	of	E Sar	n Juan	)	

the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 12th day of January, 1981

Notary Public

09-20-84 My Commission Expires