MACHINGTON: 0

BY _

5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

DEPARTMENT OF THE INTERIOR	21 - 018420
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
CHAIDDY MOTICES AND DEPORTS ON WELLS	N/A
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different	M / A
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	5
1. oil gas XX other	Nickson 9. WELL NO.
2. NAME OF OPERATOR	#21
Supron Energy Corp. % John H. Hill, et al	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Suite 020, Kysar Building	Ballard Pictured Cliffs
300 W. Arrington, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 11 T26N R8W
AT SURFACE: 1850' FSL & 790' FWL (NW SW)	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6299' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	0299 GK
TEST WATER SHUT-OFF \(\times \)	
FRACTURE TREAT	and the side of the control of the c
REPAIR WELL	(NOTE: Report results of multiple completion or zone
	change on Form 9–330.)
MULTIPLE COMPLETE :	
ABANDON*	i
(other) U. a. Alle sell	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statingluding estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinen	e all pertinent details, and give pertinent dates, irectionally drilled, give subsurface locations and
1. Spudded a 12½" hole at 12:00 A.M., 8/4/81. cement.	Drilled to 240'. Circulated
2. Ran 5 joints (203.90') of new 8 5/8", 24#,	LS, R-2 ST&C casing.
3. Set and cemented at 215.90'RKB.	
4. Cemented with 225 sx. Class "B" cement and	2% Calcium Chloride.
5. Plug down at 10:20 A.M., 8/4/81.6. Circulation good throughout job. Circulate	ed 5 barrels cement.
7. Check water shut off at 600#, with 8" 4000	
	/RII.TIVFN
	Liratiath /
į	AUG 14 1981
	OIL CON. COM.
Subsurface Safety Valve: Manu. and Type	DIST. 3 Pet @Ft.
19. I have by configuration that the foregoing is true and correct	
SIGNED WINNELD IN WILLIAMS SUPERINTENDER	Development nt DATE August 7, 1981
(This space for Federal or State of	fice use)
APPROVED BY	DATE
CONDITIONS OF APPROVAL, IF ANY:	CONEPTED FOR DECORE
NMOCC	ୟୁଗ 1 3 1981
*See Instructions on Reverse	