

F

30-045-24908

2-26-81

F. Loc. 1050/N; 1080/E

Elev. 6020 GL

Spd. 2-26-81

Comp. 3-6-81

TD 1300

PB 1249

Casing S. 7 @ 86 W 35 Sx.

Int. @ W

Sx. Pr. 2 7/8

@ 1275 W 125 Sx.

T. 1 1/4

@ 1065

Csg. Perf.

172-1178

72 40F

80/8

Prod. Stim.

577

T
R
A
N
S

I.P. 68

MCF/D After

Hrs.

SICP 235

PSI After 14

Days GOR

Grav.

1st Del.

s

TOPS		NITD	Well Log	TEST DATA						
Kirtland	80	C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Fruitland	926	C-104 7-30-81	Electric Log							
Pictured Cliffs	1171		C-122							
Cliff House		Ditr	Dfa							
Menefee		Datr	Dac							
Point Lookout		BP 1140 DHC 160								
Mancos										
Gallup										
Sonotee										
Greenhorn										
Dakota										
Morrison										
Entrada										

S. Gallegos PC SJ s 24 T 26N R 12W UA oper. Jerome P. McHugh

Lsa. Chaco Plant

No. 22