

5 - USGS

2 - Pioneer

1 - File

Form 9-331
Dec. 1973Form Approved.
Budget Bureau No. 42-R1424UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR
Jerome P. McHugh
3. ADDRESS OF OPERATOR
P O Box 208, Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 830' FNL - 2070' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE
N00-C-14-20-4322
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo Allotted
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Chaco Plant
9. WELL NO.
18R
10. FIELD OR WILDCAT NAME
P.C. Undesignated
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 13 T26N R12W
12. COUNTY OR PARISH
San Juan
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
5990' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See reverse side for surface casing, 3-10-81, and 2-7/8" csg., 3-15-81.

RECEIVED FOR RECORD

MAR 23 1981

FARMINGTON DISTRICT

BY Jim L. Jacobs

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Jim L. Jacobs TITLE Agent DATE 3-16-81


(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

FPMOCC

dp dukan production corp.

Jerome P. McHugh
Chaco Plant #18R
830' FNL - 2070' FWL
Sec 13 T26N R12W
San Juan County, NM



MORNING REPORT

- 3-10-81 Rosenbaum constructed location. Moved in and rigged up Morrow Drlg. Co. rig. Spudded 8-3/4" hole at 1:00 p.m. 3-9-81. Drilled to 89' GL. Start to pick up 7" csg. Rig broke down. Shut down for repairs.
- 3-11-81 Repaired rig. Ran 2 jts 7" OD, 23#, 8 Rd, ST&C csg. T.E. 87.35' set at 88' GL. Cemented w/ 35 sx class "B". P.O.B. at 10:30 a.m. 3-10-81. W.O.C.
- 3-12-81 Drlg. 5" hole at 600' w/ wtr.
- 3-13-81 Drlg. 5" hole at 1120'
- 3-14-81 T.D. 1340' - Finished drilling 5" hole. Conditioned hole. P.O.H. and ran S-Gamma Ray & Density logs by Southwest Survey. Prep to run 2-7/8" tbg. for csg.
- 3-15-81 T.I.H. and laid down drill pipe. Rigged up and ran 55 jts. 2-7/8" OD, 6.4#, 10 Rd., CW-55 10 Rd, NEUE tbg for csg. T.E. 1334.91' set at 1332' GL. Cemented w/ 75 sx 2% Lodense w/ 1/4# cello flake per sx followed by 50 sx class "B" neat w/ 1/4# cello flake per sx. Good mud returns while cementing. Cement circulated (approx. 4 bbls.) - P.O.B. at 1:00 p.m. 3-14-81.