## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9–331 Dec. 1973	Form Approved.  Budget Bureau No. 42–R1424			
UNITED STATES	5. LEASE			
DEPARTMENT OF THE INTERIOR	M-28759			
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME			
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME			
4	Federal			
1. oil gas X other	9. WELL NO.			
2. NAME OF OPERATOR	#12-14			
Southland Royalty Company	10. FIELD OR WILDCAT NAME			
3. ADDRESS OF OPERATOR	-Basin Dakota/Gallegos Gallup			
P.O. Drawer 570, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA			
below.)	Section 12, T26N, R11W			
AT SURFACE: 840' FSL & 1800' FWL	12. COUNTY OR PARISH 13. STATE			
AT TOP PROD. INTERVAL:	San Juan New Mexico			
AT TOTAL DEPTH:	14. API NO.			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,				
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)			
DESCRIPTION APPROVAL TO CURCIOUENT REPORT OF	6463' GR			
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  SUBSEQUENT REPORT OF:  SUBSEQUENT REPORT OF:	1001			
REPAIR WELL	(NOTE: Report results of multiple completion or zone			
PULL OR ALTER CASING	change on Form 9-3300 P. C.			
MULTIPLE COMPLETE	OIL DIST. 3			
ABANDON*	OIL DIST.			
(other) Spud & Casing Report X				
The second secon				
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	irectionally drilled, give subsurface locations and			
4 14 01 Chyddod 12 1/44 cymfaca bala at 5:0	0 D M 4-14-81 and drilled			

Spudded 12-1/4" surface hole at 5:00 P.M. 4-14-81 and drilled to total depth of 234'. Ran 5 joints (213.82') of 8-5/8", 24#, K-55 casing set at 229'. Cemented with 150 sacks of Class "B" with 1/4# flocele per sack & 3% CaCl2. Plug down at 3:00 A.M. 4-15-81. Cement circulated to surface.

Subsurface Safety Valve: Manu. and Type					Set @	Ft.		
18. I hereby certify that the foregoing is to SIGNED STREET STREET	rue and corr	ect Drilling	Clerk DA	NTE _	April 16, 1981			
(This space for Federal or State office use)								
APPROVED BY		E	1	DATE	ACSEPTED FUR RECOR			

APR 21 1981

ũΥ.

\*See Instructions on Reverse Side

FAMILINGTON DISTRICT