

O.H. Randel #9

N-10-26N-11W

Energy Reserves Group, Inc.

F

30-045-25133

8-5-81

F. Loc. 1090/S:1600/W Elev. 6326 GL Spd. Comp. TD PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @
Csg. Perf. Prod. Stim.

T
R
A
N
S

I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. Ist Del. s

TOPS		NI TD	X	Well Log	TEST DATA						
					Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-103		Plat X							
Fruitland		C-104		Electric Log							
Pictured Cliffs				C-122							
Cliff House		Ditr		Dfa							
Menefee		Datr		Dac							
Point Lookout											
Mancos											
Gallup											
Sanostee											
Greenhorn											
Dakota											
Morrison											
Entrada											
		160									

P
O
W. Kutz PC Co. SJ s 10 T 26N R 11W UN Oper Energy Reserve Group Loe. O.H. Randel No. 9

DRAWER 600
FARMINGTON, NEW MEXICO 87499

February 8, 1983

CERTIFIED MAIL

Energy Reserves Group, Inc.
P. O. Box 3280
Casper, Wyoming 82602

Gentlemen:

Reference is made to your Applications for Permit to Drill (APDs) wells No. 9 and 10 O. H. Randel, SE $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 10 and NW $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 9, respectively. Both are in T. 26 N., R. 11 W., San Juan County, New Mexico, lease New Mexico 03153. As discussed with Mr. William J. Piant of your Company on February 4, 1983, the subject APDs are rescinded and returned due to drilling operations not being commenced within a six month extension period following the original approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in assessment of liquidated damages.

Sincerely yours,

"Orig. Sgd." Jim F. Sims

James F. Sims
District Oil and Gas Supervisor

Enclosures

cc: NMOCC

RECEIVED
FEB 10 1983
OIL CON. DIV.
DIST. 3