

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well Gas	API # (assigned by OCD) 30-045-25259
2. Name of Operator Central Resources Inc.	5. Lease Number
3. Address & Phone No. of Operator PO Box 1247, Bloomfield NM87413 (505) 632-3476	6. State Oil & Gas Lease # E-3148-7
4. Location of Well, Footage, Sec., T, R, M Sec. 32, T-26-N, R-12-W, NMPM, San Juan County Unit I, 1850' FSL and 790' FEL	7. Lease Name/Unit Name Chaco Wash <i>Cem</i>
	8. Well No. #2
	9. Pool Name or Wildcat Bisti Farmington
	10. Elevation: 6102'

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other -

13. Describe Proposed or Completed Operations

1-8-99 Road rig and equipment to location, stuck in sand. Pull rig out and set on jacks. RU rig. SDFD.

1-11-99 RU rig and relief line. Well pressure: casing 50# and tubing 0#, bleed well down. ND wellhead. Release packer. POH and LD 19 joints 1-1/4" tubing and packer. Attempt to establish rate into open perforations pumping 3 bbls water, pressure increased to 800#. RIH with tubing to 645'. Plug #1 with 12 sxs Class B cement inside 2-7/8" casing from 645' to 200'. POH with tubing. RD rig and MOL. Road cementing equipment back. RU wireline unit and RIH, tag cement at 300'. Perforate 2 bi-wire squeeze holes at 201'. Attempt to establish circulation out bradenhead, pressured up to 1800#. Hooked up to bradenhead valve and attempted to pump down, pressured up to 1500# with 1/4 bbl water. Perforate at 153' with 2 bi-wire squeeze holes. Unable to establish circulation. H. Villaneuva, NMOCD, approved procedure change to bullhead down casing. Plug #2 with 16 sxs Class B cement pumped down 2-7/8" casing to cover squeeze holes at 201' and 153', and surface casing shoe, final 600# squeeze pressure. Shut in well and WOC. SDFD.

1-12-99 Safety Meeting. Dig out wellhead and cut off. Found cement down 5' in 7" annulus and 2-7/8" casing full. Mix 15 sxs Class B cement, top 7" casing and install P&A marker.

H. Villaneuva, NMOCD was on location 1/11/99.

SIGNATURE *Rodney Z. Seale* 2-13-99 District Manager January 15, 1999

(This space for State Use)

Approved by ORIGINAL SIGNED BY E. VILLANUEVA

Title

DEPUTY OIL & GAS INSPECTOR, DIST. #3

Date

MAR - 2 2000