Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

RIR	10	F-C	170	\sim	
IND		1	1 I O		חר

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPL	ICATE – Other instruc	tions on	4 (FREIS)	Majorie	7. If Unit or CA Central Bisti	/Agreement, Name and/or No. Unit	
X Oil Well Gas Well	Other	14	AUG	2001	8. Well Name a		
2. Name of Operator Central	Resources	121	RECE	Van 23	Central Bisti		
Elm Ridge Resources, Inc.		=	OIL COM	Law. Ed	9. API Well No.		
3a. Address 3b.		16. Hone N 505-632-3	No. (i rializă e a R 476	rea code)	30-045-25347 10. Field and Pool, or Exploratory Area		
PO Box 189 Farmington, NM 87499 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Bisti Lower Gallup			-	
660' FSL & 1980' FWL	· · · · · · · · · · · · · · · · · · ·			2	11. County or Parish, State		
Sec. 31-T26N-R12W					San Juan, New Mexico		
12. CHECK APPROPRIATE BOX(E	S) TO INDICATE NATURE O	F NOTICE,	, REPORT,	OR OTHER DA	ТА		
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture New Con	struction	Production (S Reclamation Recomplete	,	Water Shut-Off Well Integrity Other	
			Plug and Abandon Temporarily Abandon				
X Final Abandonment Notice	Convert to Injection	Plug Bac		Water Dispos			
3. Describe Proposed or Completed Operation If the proposal is to deepen directionally Attach the Bond under which the work Following completion of the involved operating has been completed. Final Abadetermined that the site is ready for final inspecting with the site is ready for final inspection with the site is ready for final inspection. With the site is ready for final inspecting with the site is ready for final inspection. With the work of the site is ready for final inspection. With the work of the proposal inspection of the involved operation. With the work of t	or recomplete horizontally, give sub will be performed or provide the Bration rations. If the operation results in a indeniment Notices shall be filed only tion.) and abandoned the Centro to 500 PSI - did not hold 1950'. RIH w/cement retainer - something broke.	surface location No. on file involtiple compared in the surface of	ons and measure with BLM/, nit #81 or nit #81 or nit #81 or nit #82-jts 2-3, ulation up circulate	ured and true vertical BIA. Required substance plants are with the plants of the plant	I depths of all perequent reports shall interval, a Form 3 have been completed. I as follows: w/2% CaCl. I 1916'. Predint casing and ent. RIH w/wi	minent markers and zones. I be filed within 30 days sideo-4 shall be filed once ted, and the operator has MIRU cementers, est WOC RIH w/wireline - essure test casing - d pump 50 sx Class "B" ireline - tag cement @	
1693'. Perf. holes @1230'. RI							
Class "B" cement inside and ou cement inside and outside casi cement. Circulate cement to s witness procedure.	ng. RIH w/wireline perf @	269'. E	st. circula	tion through B	radenhead -	pump 101 sx Class "B"	
14. I hereby certify that the foregoing is tru	ie and correct						
Name (Printed Typed) Trudy Grubelnik			Title Production Technician				
Signature Middle Shirt Chick		Date	Date July 31, 2001				
7	THIS SPACE F	OR FEDER	AL OR STA	TE USE			
Approved by		Tit	le		Date		
Conditions of approval, if any, are attached, certify that the applicant holds legal or equiwhich would entitle the applicant to conduct	table title to those rights in the subje	arrant or Offict lease	ice		ACCEPTE	FOR RECORD	
Title 18 U.S.C. Section 1001, makes it a criffraudulent statements or representations as to	me for any person knowingly and will any matter within its jurisdiction.	lifully to mak	e to any depa	rtment or agency of	the United States a	ny false fictitions or 5 2001	