

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other

2. NAME OF OPERATOR
VERYL F. MOORE

3. ADDRESS OF OPERATOR
2605 HIGHLAND PLACE, FARMINGTON, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1805' FNL & 1495' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:
TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other)

SUBSEQUENT REPORT OF

RECEIVED
JAN 5 1983

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

5. LEASE

CON HALE

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

1J

10. FIELD OR WILDCAT NAME

BALLARD PICTURE CLIFF

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC. 24 T26N R8W

12. COUNTY OR PARISH

SAN JUAN

13. STATE

NEW MEXICO

14. API NO.

NM 02901

15. ELEVATIONS (SHOW DF, KDB, AND WD)

6968' KDB

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-21-82: MIRU James Drilling. Spud well 12:10 PM 12-20-82. Drill 130' of 9 7/8 hole. 0° dev. at 130'. Run 121' of 7 5/8 26.4# surface pipe set at 125' KB. Cemented w/80 sks class B neat w/3% CC. Circulated 15 sks to surface.

12-25-82: Drill 2950' of 6 1/4 hole. Rig up Dresser and run I.E.S. and Density logs. Rig up and run 2933' of 2 7/8 tubing for casing. Rig up National Cementers and cement w/285 sks 65/35 poz; tailed in w/185 sks 50/50 poz. Circulated throughout job. Bumped plug w/2000#. Released pressure, plug held OK. Plug down 7:00 AM 12-25-82.

12-26-82: Rig up Wilson survey. Ran temp. survey. Top of cement 1100'.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Veryl F. Moore TITLE owner DATE 12-26-82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 12-26-82
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMOC COM

JAN 05 1983

FARMINGTON DISTRICT