

ROBERT L. BAYLESS

Blackhills #1
Sec. 25, T26N, R13W
SW/4SW/4
San Juan County, NM

SLOPE TEST

<u>Depth</u>	<u>Hole Deviation</u>
92'	1/4°
900'	1/2°
1,390'	3/4°
1,450'	3/4°

State of New Mexico)
) ss
County of San Juan)

I, Kevin H. McCord, Petro. Engineer, being first duly sworn,
depose and state that the above and foregoing depth and hole
deviation figures are true and correct to the best of my
information and belief.

Kevin H. McCord

Subscribed and sworn before me this 14th day of July, 1983.

Carmel Gutierrez
Notary Public

My Commission Expires

5/11/85

