

MERRION OIL & GAS CORPORATION

Hickman A 1R
NE/SW Sec. 10, T26N, R12W
San Juan County, New Mexico

SLOPE TESTS


<u>Depth</u>	<u>Hole Deviation</u>
94'	1/4
228'	3/4
736'	1
1238'	1-1/2
1551'	1
2052'	3/4
2522'	3/4
3022'	3/4
3515'	3/4
4013'	1/2
4540'	1
5048'	1/2
5259'	1/2
5280'	1/2


RECEIVED
JUL 12 1988
OIL CON. DIV.
DIST. 3

State of New Mexico)
) ss
County of San Juan)

I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 11th day of July.





Notary Public

My Commission Expires 11-20-89