

Delhi Taylor A #7

A-17-26N-11W

MERRION OIL & GAS CORP.

F

30-045-28046

07-31-90

F. Loc. 920/N; 990/E Elev. 6215 GL Spd. _____ Cu. ft. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 MCF/D After _____ Hrs. SICIP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NTD	Well Log	TEST DATA						
				Schd.	PC	Q	PW	PD	D	Ref. No.
Ojo Alamo		C-103	Plat X							
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Cracra		Datr	Dac							
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
		Acres E/320								

P
o
o

BasinFrCoal Co. SJ S 17 T 26N R 11W UA Oper. Merrion Oil & Gas Lse. Delhi Taylor A No. 7



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington Resource Area

1235 Laplata Highway

Farmington, New Mexico 87401



IN REPLY REFER TO:

NM-33047 et al. (WC)
3162.3-1 (019)

Merrion Oil & Gas Corporation
P.O. Box 840
Farmington, NM 87499

OCT. 10 1991

RECEIVED
OCT 11 1991
OIL CON. DIV
DIST. 3

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- ✓ 1. 5 Hi Roll, sec. 35, T. 27 N., R. 13 W., San Juan Co., NM, lease NM-33047.
- ✓ 2. 2 Nelson, sec. 9, T. 26 N., R. 12 W., San Juan Co., NM, lease SF-078944-A.
3. 11 Southland, sec. 9, T. 26 N., R. 13 W., San Juan Co., NM, lease NM-12235.
- ✓ 4. 8 Southland, sec. 10, T. 26 N., R. 13 W., San Juan Co., NM, lease NM-12235.
5. 1 Star Federal 30, sec. 30, T. 26 N., R. 12 W., San Juan Co., NM, lease NM-0560223.
- ✓ 6. 5 Morgan, sec. 31, T. 27 N., R. 12 W., San Juan Co., NM, lease SF-080238-A.
- ✓ 7. 7 Delhi Taylor A, sec. 17, T. 26 N., R. 11 W., San Juan Co., NM, lease SF-079679.
8. 2 Frontier, sec. 5, T. 26 N., R. 12 W., San Juan Co., NM, lease SF-081102-A.
9. 9 Southland, sec. 11, T. 26 N., R. 13 W., San Juan Co., NM, lease NM-12235.
10. 10 Southland, sec. 3, T. 26 N., R. 13 W., San Juan Co., NM, lease NM-12235.
- ✓ 11. 2 Serendipity, sec. 26, T. 26 N., R. 13 W., San Juan Co., NM, lease NM-33031.

As discussed with Steven Dunn of your company on, October 8, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

ABANDONED LOCATION

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410