

F


30-045-28544

05-20-91

F. Loc. 790/S; 2200/W Cu. ft. Elev. 6045 GL Spd. Comp. TD PB
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @
 Csg. Perf. Prod. Stim.

T
R
A
N
S

BO/D Grav. 1st Del. Gas
 I.P. MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS		NIID	X	Well Log	TEST DATA								
Ojo Alamo		C - 103		Plat	X	Schd.	PC	Q	PW	PD	D	Ref. No.	
Kirtland		C - 104		Electric Log									
Fruitland				C - 122									
Pictured Cliffs		Ditr		Dfa									
Chacra		Datr		Dac									
Cliff House													
Menefee													
Point Lookout													
Mancos													
Gallup													
Greenhorn													
Dakota													
Entrada													

Acres S/320

P
o
o

BasinFRCoal Co. SJ S 20 T 26N R 12W UN Oper. Merrion O & G Corp. Lse. Star Federal 20 No. 1

Star Federal 20 #1

N-20-26N-12W

MERRION OIL & GAS CORP.

NM-0560223 (WC)
3162.3-1.0 (019)

APR. 28 1992

RECEIVED

APR 29 1992

**OIL CON. DIV
DIST. 3**

Merrion Oil & Gas Corporation
PO Box 840
Farmington, NM 87499

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 1 Star Federal 20, SW $\frac{1}{4}$ Sec. 20, T. 26 N., R. 12 W., San Juan County, New Mexico, lease NM-0560223. As per the Sundry Notice dated April 6, 1992, the subject APD is rescinded and returned as requested.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ William F. Blackard

For John L. Keller
Chief, Branch of Mineral Resources

1 Enclosure

cc:
New Mexico Oil Conservation Division, Aztec, NM

ABANDONED LOCATION