## L & B Speed Drill, Inc.

## James L. Ludwick

P.O. BOX 70 • FARMINGTON, NEW MEXICO 87499-0070 • (505) 325-1079

July 26, 1999

MERRION OIL & GAS CORPORATION 610 REILLY AVE. FARMINGTON, NM 87401

Re: Directional Survey Well Slice No. 1 825' FSL & 923' FWL Sec. 4, T26N, R12W San Juan County, NM

Below is the directional survey for your well Slice No. 1.

123' 1/2°

6001 1/2°

1100' 3/4°

1375' 3/4°

ACKNOWLEDGEMENT

STATE OF NEW MEXICO

COUNTY OF SAN JUAN

The forgoing instrument was acknowledge before me this 26th

My commission expires: /// 18/85