L & B Speed Drill, Inc.

P.O. BOX 70 • FARMINGTON, NEW MEXICO 87499-0070 • (505) 325-1079

DATE: 10/14/2000 TO: MERRION OIL & GAS 610 REILLY AVE. FARMINGTON, NM 87499 34-6-15-36257 Re: Directional Survey Well Hiccup No. A 2 Sec. 3, T26N, R12W San Juan County, NM Below is the directional survey for your well Hiccup NO. A2 130' 1/2° 6001 1/2° 1100' 3/4° 1550**'** 1° **ACKNOWLEDGEMENT** STATE OF NEW MEXICO COUNTY OF SAN JUAN SIGNED & ACKNOWLEDGED BY: