

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
Budget Bureau No. 1004-0135

Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

| | |
|--|--|
| 1. Type of Well Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/> | 5. Lease Designation and Serial No. SF-080384-B |
| 2. Name of Operator Merrion Oil & Gas Corporation (14634) | 6. If Indian, Allottee or Tribe Name Navajo Allotted Surface |
| 3. Address and Telephone No. 610 Reilly Avenue, Farmington, NM 87401-2634 (505) 327-9801 | 7. If Unit or CA, Agreement Designation |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 725' fsl & 986' fwl (sw sw) Section 3, T26N, R12W | 8. Well Name and No. HICCUP A NO. 2R |
| | 9. API Well No. 30-045-31009 |
| | 10. Field and Pool, or Exploratory Area Basin Fruitland Coal |
| | 11. County or Parish, State San Juan County, New Mexico |

| 12. CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA | | |
|---|---|--|
| TYPE OF SUBMISSION | TYPE OF ACTION | |
| <input type="checkbox"/> Notice of Intent | <input type="checkbox"/> Abandonment | <input type="checkbox"/> Change of Plans |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion | <input type="checkbox"/> New Construction |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Plugging Back | <input type="checkbox"/> Non-Routine Fracturing |
| | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> Water Shut-Off |
| | <input type="checkbox"/> Altering Casing | <input type="checkbox"/> Conversion to Injection |
| | <input checked="" type="checkbox"/> Other <u>Tbg Report</u> | <input type="checkbox"/> Dispose Water |

(Note: Report results of multiple completion on Completion or Recompletion Report and Log form.)

13. Describe Proposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU JC Well Svc. ND frac valve & NU stripping head. PU & RIH w/ 2 3/8" tbg. Tag sand at +/-1315'. RU pumps & lines. Break circulation & clean out frac sand to PBTD (1562'). Never lost any fluid while cleaning out. Pull up above perfs & SD. RIH & check for fill - none. Pull up & land production string as follows: tail jt, SN & 42 jts. 2 3/8", 4.7#, J-55, EUE tbg. landed @ 1411' KB. SN @ 1382' KB. ND stripping head & NU WH. RUTS. Made 10 swab runs & recovered about 18 bbls fluid. Fluid looked clean - no sand. RD swabbing equipment. RIH w/ 2" X 1 1/4" X 12' RHAC insert pump. Ran pump on 55 ea. 3/4" plain rods. PU polish rod & stuffing box. Seat & space out pump. Hang off rods & NU horse head. Loaded tubing & tested pump - pumping OK w/ pumping unit. Left well pumping to pit. RDMOL. Release rig.

| | | |
|---|----------------------------------|-------------------------|
| 14. I hereby certify that the foregoing is true and correct | | |
| Signed <u>Connie S. Dinning</u> | Title <u>Production Engineer</u> | Date <u>8/7/02</u> |
| (This space for Federal or State office use) | | |
| Approved By <u>/</u> | Title <u></u> | Date <u>AUG 13 2002</u> |
| Conditions of approval, if any: | | |

ACCEPTED FOR RECORD

FARMINGTON FIELD OFFICE