

(SUBMIT IN TRIPLICATE)


Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Jicarilla Apache

Allottee _____

Lease No. 240



660' ~~N~~, 2310' ~~E~~

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

FEB 1963
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 5, 1963

Jicarilla 4-35

Well No. 7 is located 660 ft. from N line and 2310 ft. from E line of sec. 35

NW 1/4 of NE 1/4, Sec. 35
(1/4 Sec. and Sec. No.)

29N
(Twp.)

1W
(Range)

106M
(Meridian)

Boulder-Mancos
(Field)

Rio Arriba
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 7199 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 1-21-63, a radio-active tracer survey was run using 126 barrels lease crude to determine the feasibility of a second fracture treatment. Total load oil to recover 342 barrels.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Company of Texas, A Division of California Oil Company

Address Drawer "S"

Monahans, Texas

By J. L. Rowland

Title District Engineer