

(FURNISH IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079521-A
Unit San Juan 28-5 Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL
NOTICE OF INTENTION TO CHANGE PLANS
NOTICE OF INTENTION TO TEST WATER SHUT-OFF
NOTICE OF INTENTION TO REPAIR OR REPAIR WELL
NOTICE OF INTENTION TO HOIST OR LOWER
NOTICE OF INTENTION TO HOIST OR ALTER CASING
NOTICE OF INTENTION TO ABANDON WELL

XX

SUBSEQUENT REPORT OF WATER SHUT-OFF
SUBSEQUENT REPORT OF SEPARATING OR ALTERING
SUBSEQUENT REPORT OF ALTERING CASING
SUBSEQUENT REPORT OF SEPARATING OR REPAIR
SUBSEQUENT REPORT OF ABANDONMENT
SUBSEQUENT REPORT OF ALTERING

RECEIVED

JUL 10 1963

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

DATE ACTIVITY TO BE REPORTED TO BUREAU OF LAND MANAGEMENT

July 8

1963

Well No. 64 located 1850 ft from N line and 790 ft from E line of sec. 28
NE/4 Sec. 28 28-N 5-W N.M.P.M.
Basin Dakota Rio Arriba New Mexico

The elevation of the surface floor above sea level is 6702 ft.

DETAILS OF WORK

State of New Mexico, County of Santa Fe, BLM District of Santa Fe, Section 28, Township 28-N, Range 5-W, N.M.P.M., Rio Arriba County, New Mexico.

It is intended to change the casing program on this well in the following manner:

- 10 3/4" @ 300' w/232 sacks cement circulated to surface.
- 7 5/8" @ 3755' w/190 sacks cement to cover Ojo Alamo.
- 4 1/2" @ 7965' w/2 stage tool @ 5786', cement first stage w/100 sacks cement second stage w/100 sacks cement.

Under the authority of the Bureau of Land Management, the following work is being done on the above described well:

Company El Paso Natural Gas Company
Address Box 990
Farmington, New Mexico



Petroleum Engineer