APPROVED

JLL 6 1956 DE

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land (Office	Seat	. Fe	
	No	77	**	
Unit	36D	J _{ij} en	28-7	Unit
		Y 1(YC)		

SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRI	MOTICES	AND KEP	ORIS ON	WELLS	
NOTICE OF INTENTION TO DRILL		SUBSEQUENT	REPORT OF WATER	SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PL	ANS	SUBSEQUENT	REPORT OF SHOOT	NG OR ACIDIZING	~
NOTICE OF INTENTION TO TEST WATE	R SHUT-OFF	SUBSEQUENT	REPORT OF ALTER!	NG CASING	The same of
NOTICE OF INTENTION TO RE-DRILL O	R REPAIR WELL	SUBSEQUENT	REPORT OF RE-DRI	LLING OR REPAIR	d
NOTICE OF INTENTION TO SHOOT OR	ACIDIZE	SUBSEQUENT	REPORT OF ABANDO	ONNERS	10,00 100
NOTICE OF INTENTION TO PULL OR A	LTER CASING	SUPPLEMENT	ARY WELL HISTORY	123	3/1/2
NOTICE OF INTENTION TO ABANDON V	YELL			01:01:01:01:01:01:01:01:01:01:01:01:01:0	WEM IN
(INDICAT	E ABOVE BY CHECK MA	ARK NATURE OF REPOR	T, NOTICE, OR OTHER	DATA	
				June 28	. 19
Vell No. 22 is locate	ed 🧀 ft. fro	om. $\begin{cases} N \\ c \end{cases}$ line and	1750 ft. fr	om \mathbb{R} line of so	ec. 29
(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
Slanes		Mo arriv	ŝ.	der malco	
state names of and expected depths to Spain date 5-15-56. In 5-15-56. Total Dep	ing points, and a	sizes, weights, and les all other important pro	ngths of proposed ca oposed work)	sings; indicate muddin	g jobs, ceme
ian 5 joints 10 3/4", 125 sacks regular cens Esld 500; 30 minutes.	32.754, Arec			PAR SE BE 10	2' vit
I understand that this plan of work	must receive approval	l in writing by the Ge	ological Survey bere	m may be co	mmenced.
ompany Zi reso R t	aral Ges Comp	** **********************************			
ddress Box 997				/	
Yarzin,ton,	her horice		By S	5 Bord	?
		т	itle Petrol	eum inglieer	
		i	itie		



