UNITED STATES

	Rnaget	Bureau	No.	42-R14
EASE				

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Nº 013657 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR E1 Paso Natural Gas Company 3. ADDRESS OF OPERATOR P. O. Box 289, Farmington, N. M. 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 990' FNL, & 1650 FE1 AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME S. J. 28-6 Unit 8. FARM OR LEASE NAME S. J. 28-6 Unit 9. WELL NO. 10 10. FIELD OR WILDCAT NAME Blanco Mesa Verde 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25, T28N, R6W 12. COUNTY OR PARISH Rio Arriba New Mexico 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD)		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Temporarily repair casing leak 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen	(NOTE: Report results of multiple completion of Zero Change on Form 9–330.) MAR 2 196 OIL CON. COM. DIST. 3		
Approval has been given to set an Otis permaisolate a suspected casing failure. As of yet, this work has not been completed a evaluation period be granted, which is to becafter the packer has been set.	latch macker in order to nd a request for a 90 day		
Subsurface Safety Valve: Manu. and Type	DATE January 30, 1981		

*See Instructions on Reverse Side

JAMES F. SIMS DISTRICT OIL & GAS SUPERVISOR