DEPUTY OIL & GAS INSPECTOR

DEC 2 9 1997

Meter Number:72333
Location Name:SAN JUAN 28-5 #26
Location:TN-28 RG-05
SC-14 UL-H
2 - Federal
NMOCD Zone:OUTSIDE

Hazard Ranking Score:00

DECEIVED N APR 1 4 1997 OUL COLL DOV. DUSS. 3

## RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone  $10^{-9}$  to  $10^{-13}$  cm/sec Shale  $10^{-12}$  to  $10^{-16}$  cm/sec Clay  $10^{-12}$  to  $10^{-15}$  cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



## FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 72333 Location: SAN JUAN 28-5 # 26  Operator #: 2999 Operator Name: MERIDIAN P/L District: BLOOMFIELD  Coordinates: Letter: H Section 14 Township: 28 Range: 5  Or Latitude Longitude  Pit Type: Dehydrator X Location Drip: Line Drip: Other:  Site Assessment Date: 5:28:94 Area: 10 Run: 61
SITE ASSESSMENT	NMOCD Zone:  (From NMOCD  Maps)  Inside  Outside  Outside  (I)  Fee  (3)  Outside  Outside  (1)  Depth to Groundwater  Less Than 50 Feet (20 points)  Greater Than 100 Ft (0 points)  Wellhead Protection Area:  Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source?   (1) YES (20 points)   Horizontal Distance to Surface Water Body  Less Than 200 Ft (20 points)   (2)  Greater Than 1000 Ft (0 points)   (3)  Name of Surface Water Body  (Surface Water Body —  (Surface Water Body: Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds)  Distance to Nearest Ephemeral Stream   (1) < 100'(Navajo Pits Only)  (2) > 100'  TOTAL HAZARD RANKING SCORE:   POINTS
REMARKS	Remarks: Two Pits on Location. WILL CLOSE ONLY ONE. PIT IS DRY. LOCATION IS ON A MESA. REDUNE AND TOPE CONFIRMS D LOCATION 15 OUTSIDE V.Z.

## FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 72 333 Location: SAN Juan Coordinates: Letter: # Section 14 Towns Or Latitude Longitude Date Started: 6-29-94 Area: 10	ship: <u>28</u> Range: <u>5</u>
FIELD OBSERVATIONS	Sample Number(s): MK67  Sample Depth: Feet  Final PID Reading NS  Yes No  Groundwater Encountered (1) X (2)	PID Reading Depth <u>/c</u> Feet
CLOSURE	Onsite Bioremediation (2)  Backfill Pit Without Excavation (X) (3)  Soil Disposition:	Approx. Cubic Yarcs
REMAKKS	Pit Closure Date: 6-29-94  Remarks: FPNG IINES Marked OJOR HIT SAND STONE 10'	Pit Closec By: BE I
REM	Signature of Specialist: Mogan Xi	



## FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

_	Fiel	d ID		l.ab ID		
SAMPLE NUMBER:	M146-	7	94			
MTR CODE   SITE NAME:	72333	3		N/A		
SAMPLE DATE   TIME (Hrs):	6-29-	GY		721		
SAMPLED BY:			N/A			
DATE OF TPH EXT. ANAL.:		30/91/	(c)	30196	1	4
DATE OF BTEX EXT. ANAL.:	n ) 14		2 1	هرسستند عمده		
TYPE   DESCRIPTION:	У. С		siey/byon	1 clay t	old Stork	
REMARKS:			J 1/	•		
		RESULTS				
PARAMETER	RESULT	UNITS				
			DF	QUALI	M(g)	V(mi)
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		MG/KG		:		
TPH (418.1)	1430	MG/KG			2.02	28
HEADSPACE PID	115	PPM				
PERCENT SOLIDS	89.7	%				
Surrogate Recovery was atative:	TPH is by EPA Method 418	3.1 and BTEX is by EPA % for this sample		was accep	table.	

<b>(</b> *	*:	* *										ŧΞ	T( €	25 A	t nc	4 1	et Fe	th et	∢≭ od ro nd	1	fo eu	r m	Н							1	* *	# 3	半半半
**	发.	ž ji	<b>(</b> )	: A	*	浓:	k)						Ä۲	1a	1	/ 5	i.s	:	el Re **	; j	or	t				水井	<b>(</b> *	* 5	¢Ψ	生;	東洋	*)	本 東 中 中
14	. 7 :				· ··.			t ii	1 4	0.0	7																						
14	5.			: ::	-:		į,	19	177	4	<u>.</u>	. 40		- 1.	C.:	-																	
														D 17:																			
					.11.			is			.1	 								Ψ.													
																					114			 	i i i								