



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Betty Rivera
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

July 9, 2002

Dolores Silseth
Burlington Res O&G Co
PO Box 4289
Farmington NM 87499

Re: San Juan 28-6 Unit #56, M 11-28N-06W API 30-039-07455

Dear Dolores:

The Bradenhead test on the above well indicates a possible casing problem. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before March 15, 2002.

Place Compliance number: CTP0134462708 on all communication regarding this Directive.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

A handwritten signature in cursive script that reads "Charlie T. Perrin".

Charlie T. Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: CTP
Well File