



OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS RD. - AZTEC

87410

LAND COMMISSIONER
PHIL R. LUCERO

DIRECTOR
JOE D. RAMEY



STATE GEOLOGIST
EMERY C. ARNOLD

August 9, 1976

Mr. W. D. Dawson
El Paso Natural Gas Co.
P. O. Box 990
Farmington, New Mexico

Re: El Paso Natural Gas Co.
San Juan 28-6 Unit #137
M-14-28N-6W

Dear Mr. Dawson:

Please contact Mr. Charles Gholson of this office for a witnessed Bradenhead Test for the subject well.

The subsequent report of remedial action dated June 30, 1976, failed to indicate if a casing test was accomplished.

If there are questions, please contact us.

Yours very truly,

A. R. Kendrick
A. R. Kendrick
Supervisor, District #3

ARK:mc

xc: Oil Conservation Commission
Santa Fe, New Mexico

U. S. G. S.
Durango, Colorado

Mr. Charles Gholson
Aztec, New Mexico

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 02805

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

San Juan 28-6 Unit

8. FARM OR LEASE NAME

San Juan 28-6 Unit

9. WELL NO.

137

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 14, T28N, R6W

N.M.P.M.

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 990, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

790'S, 1450'W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6473' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Remedial work ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-16-76 MOL and RU- Killed well with water. Tagged bottom @7757' which was 68' above PBTD of 7825'. Pulled tubing.

6-17-76 Found tight spots in casing between 5600' and 5700'. Unable to run production packer.

6-18-76 Attempted to mill out tight spots with very little success. Casing scraper went to 7357' (400' additional fill on bottom)

6-19-76 Circulated hole and ran Howco E-Z drill cement retainer to 7544'. Landed tubing w/237 jts. @7513'. Shut down and wait for further evaluation.



JUL 1 1976

RECEIVED JUL 1 1976

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles W. D...

TITLE

Production Engineer

DATE

June 30, 1976

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side