UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE*
(Other instructions on re-

Form approved, Bridget Bureau No. 42 R1424. ASE DESIGNATION AND SURIAL NO.

DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY	SF 078496
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALEOTTEE OR TRINE NAME
1.	7. UNIT AGREEMENT NAME
OIL GAS WELL X OTHER .	San Juan 28-7 Unit
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
El Paso Natural Gas Company 3. Address of Operator	San Juan 28-7 Unit
PO Box 990, Farmington, NM 87401	131
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT
At surface 1680'S, 870'W	Basin Dakota 11. SEC., T., R., M., OR BLK. AND SUBVEY OR AREA
	Sec. 34, T-28-N, R-7-W NMPM
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
6189'GL	Rio Arriba New Mexic
16. Check Appropriate Box To Indicate Nature of Notice, Report, or 1	Other Data
* *	QUENT REPORT OF:
TOTAL OF INTERIOR TO	
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL ALTERING CASING
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING	ABANDONMENT*
(0ther)	
(Note: Report result	ts of multiple completion on Well pletion Report and Log form.)
3-19-73 Spudded well and drilled surface hole. Ran 7 joint H-40 surface casing, 223' set at 225'. Cemented cement, circulated to surface.	
- MAR 30 1973	
CAL CON. COM.	2. S.
DIST. 3	
18. I hereby certify that the foregoing is true and correct SIGNED TITLE Petroleum Engineer	DATE _March 27, 1973
(This space for Federal or State office use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE