Form 9 331 (May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR (Officer Instructions on resonance)

		GEOLOGICAL SURV	/EY		SF 078496-		
	SUNDRY NO	6 IF INDIAM, ALI	LOTTEN OR TROP SAME				
I, 01 GAN (52)					7. UNIT AGREEMENT NAME		
WHI.E.	WHILE I WELL A OTHER					San Juan 28-7 Unit	
2. NAME OF OPERATOR 11 Dago Matural Cas Campany					8. MARN OR LEASE NAME San Juan 28-7 Unit		
El Paso Natural Gas Company 3. Address of Operator					9. WELL NO.		
	x 990, Farmi		225				
	ELL (Report locatio		10. FIELD AND POOL, OR WILDCAT				
At surface					Basin Dako	Basin Dakota	
970' N, 860' E					11. SEC., T., R., M SURVEY OR	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
	•				Sec. 34, 1	?-28-N, R-7-W	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)			NMPM 12. COUNTY OR PARISH 13. STATE		
21, 12,			nemer bi	, 11, 01, 000,	Rio Arrib		
16.		6091' GL				THOW PORTEO	
10.			icate N	lature of Notice, Report, o			
	NOTICE OF INT	TENTION TO:		SUBS	SEQUENT REPORT OF:	1	
TEST WATER S	SHUT-OFF	PULL OR ALTER CASING	_	WATER SHUT-OFF	X REPAIR	TING WELL	
FRACTURE TRE		MULTIPLE COMPLETE		FRACTURE TREATMENT	X ALTER	ING CASING	
SHOOT OR ACH	DIZE	ABANDON*		SHOOTING OR ACIDIZING	ABAND	ONMENT*	
REPAIR WELL (Other)		CHANGE PLANS			ults of multiple comple mpletion Report and L		
17. DESCRIBE PROPORTION OF PROPOSED WO nent to this v	rk. II well is dire	OPERATIONS (Clearly state all ctionally drilled, give subsurf	pertinen ace locat	t details, and give pertinent da- tions and measured and true ver	tes, including estimate	d date of starting any	
03-19-77	O3-19-77 T.D. 3036'. Ran 80 joints 7", 20#, K-55 intermediate casing, 3022' set at 3036'. Cemented with 248 cu. ft. cement. WOC 12 hours, held 1200#/30 minutes. Top of cement at 2000'.						
03-24-77 T.D. 7212'. Ran 225 joints 4 1/2", 10.5 & 11.6#, K-55 production casing, 7201' set at 7212'. Float collar set at 7205'. Cemented with 647 cu. ft cement. WOC 18 hours. Top of cement at 2400'.						on casing, 647 cu. ft.	
07-03-77	07-03-77 PBTD 7205'. Tested casing to 4000#, ok. Perfed 6987', 6996', 7012', 7108', 7114', 7120', 7144', 7187' with 1 SPZ. Fraced with 70,000#40/60 sand and 81,060 gallons treated water. No ball sets dropped. Flushed wi 4536 gallons water.						
					3 1977		
				OIL CON	H. COM- ST. 3		
18. I hereby certif	y that the foregoing	; is true and correct					
SIGNED	. D. Du	co TITI	Æ	Drilling Clerk	DATE	uly 5, 1977	
(This space fo	r Federal or State	office use)					
APPROVED B	Y	TITL	Æ		DATE		
	OF APPROVAL, IE			. 1/	DAIN		