Meter Number:90168

Denny &. For Location Name: VALENCIA CANYON UNIT #24 DEPUTY OIL & GAS INSPECTOR


DEC 2 9 1997

Location:TN-28 RG-04 SC-15 UL-D

2 - Federal

NMOCD Zone:OUTSIDE

Hazard Ranking Score:00



RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

10⁻⁹ to 10⁻¹³ cm/sec Sandstone 10⁻¹² to 10⁻¹⁶ cm/sec Shale 10⁻¹² to 10⁻¹⁵ cm/sec Clav

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



FIELD PIT SITE ASSESSMENT FORM EL PA

GENERAL	Meter: 90/68 Location: VALGUCIA CANYON UNIT #24 Operator #: 0203 Operator Name: AHOCO P/L District: BLOOMFIELD Coordinates: Letter: D Section 15 Township: 28 Range: \$9 am Or Latitude Longitude Pit Type: Dehydrator Location Drip: X Line Drip: Other: Site Assessment Date: 5-19-94 Area: 10 Run: 62			
SITE ASSESSMENT	NMOCD Zone: (From NMOCD (From NMOCD Maps) Inside Outside Outside (I) Fee (3) Outside (2) Indian Depth to Groundwater Less Than 50 Feet (20 points) Greater Than 100 Ft (0 points) Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; is it less than 200 ft from a private domestic water source? (1) YES (20 points) Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) (2) Greater Than 1000 Ft (10 points) (2) Greater Than 1000 Ft (0 points) (3) Name of Surface Water Body (Surface Water Body (Surface Water Body: Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream (1) < 100'(Navajo Pits Only) (2) > 100' TOTAL HAZARD RANKING SCORE: POINTS			
REMARKS	Remarks: Dic-Papaffau LIQUIDS IN PIT DNE PIT ON COCATTON			

(SP3190) 04/08/94

FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 40/68 Location: Valencia Canyon Coordinates: Letter: D Section is Township: 28 Range: 4 Or Latitude Longitude Date Started: 6-16-94 Area: 10 Run: 62				
FIELD OBSERVATIONS	Sample Number(s): \(\begin{align*}				
CLOSURE	Remediation Method : Excavation				
	Soil Disposition: Envirotech (1) (3) Tierra Other Facility (2) Name: Pit Closure Date: 6-16-94 Pit Closed By: BEZ				
REMARKS	Remarks: Wet Pit EPN/n live Markers				
	Signature of Specialist: Vale Wilson				



FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

	Field ID	Lab ID	
SAMPLE NUMBER:	VW 215	9452/68	
MTR CODE SITE NAME:	90168	N/A	
SAMPLE DATE TIME (Hrs):	Le-16-94	1515	
SAMPLED BY:	N/A		
DATE OF TPH EXT. ANAL.:	6-20-94	(6/20/94	
DATE OF BTEX EXT. ANAL.:	ب) ۾	NIR	
TYPE DESCRIPTION:	V (-	Gray organise sand or clay	
REMARKS:			
· · · · · · · · · · · · · · · · · · ·	RESULTS		

PARAMETER	RESULT	UNITS	QUALIFIERS			
			DF	Q	M(g)	V(ml)
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		MG/KG				
TPH (418.1)	240 244	MG/KG			\$ 1.99	28
HEADSPACE PID	47	PPM				
PERCENT SOLIDS	84.9	%				

- TPH is by EPA Method 418.1 and BTEX is by EPA Method 8020 -

The Surrogate Recovery was at Narrative:	-NA	% for this sample	All QA/QC was acceptable.	
				_
DF = Dilution Factor Used				_

Approved By: Farboli.	Date:	
-----------------------	-------	-------------

********************************** Test Method for Oil and Grease and Fetroleum Hydrocarbons in Water and Soil Perkin-Elmer Model 1600 FT-IR Analysis Report ******************* 94/06/20 14:09 Sample identification 74546B Initial mass of sample, o ..790 Volume of sample after extraction, ml 13.000 Patroleum hydrocarbons, ppm Net absorbance of hydrocarbons (2930 cm-1)

