

P

30-039-21636

2-1-78

F. Loc. 1610/N; 830/E Elev. 5933 GL Spd. 7-9-78 Comp. 2-24-79 TD 7021 PB 7005
 Casing S. 958 @ 206 W 224 Sx. Int. 1 @ 2794 W 265 Sx. Pr. 42 E @ 7021 W 654 Sx. T. 1/2 @ 6761
 Csg. Perf. 6761-6972 Prod. Stim. SWF

T
R
A
N
S

No Flow BO/D
 I.P. _____ MCF/D After _____ Hrs. _____ SICP 3240 PSI After 7 Days GOR _____ Grav. _____ 1st Del. 3-27-79 s _____

TOPS		NITD	Well Log	TEST DATA								Ref. No.
				Schd.	PC	Q	PW	PD	D			
Kirtland		C-103	Plot									
Fruitland		C-104 <u>3-15-79</u>	Electric Log	<u>5/4/79</u>	<u>1884</u>	<u>384</u>	<u>363</u>	<u>942</u>	<u>318</u>	<u>5-10</u>		
Pictured Cliffs		<u>6-25-79</u> <u>2°</u>	C-122	<u>13/22/80</u>	<u>NGP</u>							
Chaco Cliff House	<u>3460</u> <u>4150</u>	Ditr <u>5-10-79</u>	Dfo <u>3-27-79</u>	<u>9/4/83</u>	<u>NGP</u>							
Menefee		Datr	Dec	<u>9/4/85</u>	<u>1637</u>	<u>119</u>	<u>484</u>	<u>655</u>	<u>112</u>			
Point Lookout	<u>4736</u>			<u>2-26-87</u>	<u>0</u>	<u>well is clogged off</u>						
Mancos				<u>1988</u>	<u>NGP</u>							
Gallup	<u>5800</u>											
Sanostee												
Greenhorn	<u>6666</u>											
Dakota	<u>6851</u>											
Morrison												
Entrada												
		<u>Tenn Dill G</u> <u>LEUNG</u>										

PO 6853
 2-26-87 0 well is clogged off
 1988 NGP
 ZONE ABAND. 1-16-93
 E/320

P
O

San Juan 28-7 U No. 249