UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE **CHANGE ZONES** ABANDON* (other)

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 079729 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil gas X other	Valdez 9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company	2 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401	Choza Mesa PC Ext. 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1640'N, 1140'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 16,T-28-N, R-4-W N.M.P.M. 12. COUNTY OR PARISH Rio Arriba New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 7429 G.L.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	1423 0.1.

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 4559'. Ran 142 jts. 2 7/8", 6.4#, J-55 production casing, 4549'. set at 4559'. Baffle set at 4549'. Cemented w/285 cu. ft. cement. 7-18-79: WOC 18 hours. Top of cement at 4100'.

