4-10-8

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 080516 A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELL (Do not use this form for proposals to drill or to deepen or plug back to a diffreservoir. Use Form 9–331–C for such proposals.)	
1. oil well other 2. NAME OF OPERATOR PASO Natural Gas Company 3. ADDRESS OF OPERATOR 289, Farmington, NM 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space below.) AT SURFACE: 1590'N, 1900'W AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOT REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	NMPM 12. COUNTY OR PARISH 13. STATE New Mexico 14. At No. 16. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 05.18 GI
including estimated date of starting any proposed work. If we measured and true vertical depths for all markers and zones pe 1: Spudded well. Drilled surfage hol	y state all pertinent details, and give pertinent dates, il is directionally drilled, give subsurface locations and ritinent to this work.)* e. Ran 5 joint of 13 3/8",
48#, H-40 surface casing 219 set cement. Circ. to surface. WOC 12	at 234'. Cemented w/324 cf.
	ACCEPTED FOR RECORD
	APR 21 1981
1000 1001 1000 1000 1000 1000 1000 1000	FARMINGTON DISTRICT BY
Subsurface Safety Valve: Manu. and Type	Set @ Ft.

His 20 TITLE Drilling ClerkDATE April 13, 1981

(This space for Federal or State office use)

APPROVED BY _ CONDITIONS OF APPROVAL, IF ANY:

18. I hereby certify that the foregoing is true and correct

__ TITLE __

_____ DATE _