AFFIDAVIT

TO:

New Mexico Oil & Gas Conservation Commission
THIS IS TO CERTIFY THAT:

The following is a true and correct report of deviation tests made by CIRCLE "A" DRILLING COMPANY during the drilling of PUBCO PETROLEUM CORPORATION'S State Well No. 33, drilled in Unit N, Section 32, Township 27 North, Range 9 West, San Juan County, New Mexico.

Depth	Deviation	
315 700 994 1,497 1,490 1,763 2,616 3,476 2,649 3,649 4,702 5,698 5,494 5,690 6,690 6,690	1/4° 3/4° 1/2° 1/2° 1/2° 1/4° 3/4° 3/4° 1/4° 1/2° 1/2° 1/2° 1/2° 1/4° 1/4° 1/4°	COLL SOCIAL COM

CIRCLE "A" DRILLING COMPANY

By: Minna Will

Title: Jalpush

STATE OF NEW MEXICO
COUNTY OF SAN JUAN

Alph Tituch

My commission expires:

My Commission Expense common, 20, 1463