

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 07232
Unit Belack

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

APR 11 20, 19 50


Well No. 16-C (P) is located 210 ft. from (N) line and 200 ft. from (E) line of sec. 33
33 Sec. 33 27N 8W N.H.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco H.V. Est.-So. Blanco San Juan New Mexico
 (Field) (P.C. Est.) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6751 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud date 4-18-50.
On 4-19-50. Total Depth 175'.
Ran 6 joints 10 3/4", 32.75#, spiral weld casing (162') set at 173' with 200
sucks regular cement, 3/4" Cel, 1/2" Cel, and 1/4" Floccs/sk, circulated to surface.
Held 500# for 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 197
Farmington, New Mexico

By ORIGINAL SIGNED B.H. MEANS
Title Dist. Sales Engineer



--	--	--	--