


Land Office Santa Fe
Lease No. 21 63002 A
Unit _____

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 25, 1959

Well No. 5 is located 1500 ft. from N line and 1000 ft. from E line of sec. 25

27N (Twp.) 6E (Range) 11W (Meridian)
San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6001 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-1-59

See item number on 3 1/2" welllog at 2187' in 5 1/2 logs.
Fracture upon hole 2202-00
2000 G water, Flush 12000 G, sand 20,000
2000 G, Treating Pressure 1500'-2000', Final
Rate 20.0 GPM



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John A. Ryan
Address Box 1100
Parade Ground, New Mexico
By John A. Ryan
Title Operator