

Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Antonio

Lease No. 77921

Unit 1041

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

....., 19 52

Well No. is located 300 ft. from [N] line and 200 ft. from [E] line of sec.

1041 (1/4 Sec. and Sec. No.) 77921 (Twp.) 1041 (Range) 1041 (Meridian)
San Antonio (Field) San Antonio (County or Subdivision) San Antonio (State or Territory)

The elevation of the derrick floor above sea level is 600 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Vertical depth 200'.

In January, 1951: ran 200' hole to 100' depth with 100' (340') and at 240' with 200' casing regular cement. All 200' for 10' water. Top of sand is by geophysical survey 200'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Antonio Oil Co.

Address San Antonio, Tex.

By ORIGINAL SIGNED E. J. COEL

Title Geological Survey