


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 67808
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED
NOV 1959
U.S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 3 is located 990 ft. from N line and 1650 ft. from E line of sec. 22
NE 1/4 NE 1/4 Sec. 22 27 N 11 E NA-PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Kuts Canyon Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

At total depth 6781' we took well over from British American Oil
Producing Co. We ran 5 1/2" O.D. casing to total depth and cemented
bottom with 150 sax 4% Gel and 50 sax regular and cemented through
Baker stage collar at 2222' with 100 sax regular cement. After conclusion
of both jobs stage tool closed O.K.

RECEIVED
NOV 1959
OIL CON. COM.
DIST. 2

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.
Company Western Development Company of Delaware
Address P.O. Box 427
Artesia, New Mexico
By _____
Title Vice President

