



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Santa Fe**  
Lease No. **78589**  
Unit **1**  
Survey **1**  
Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<b>Report of sand water fracture</b>	<b>XX</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 1, 1959

Scott

Well No. **8** is located **990** ft. from **[N]** line and **1650** ft. from **[E]** line of sec. **22**

**NW 1/4 NE 4 Sec. 22** **27 N** **11 W** **NMPM**

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

**W. Kutz Canyon Dakota** **San Juan** **New Mexico**

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We rigged up on October 28th and drilled out cement stage collar at 2222'. Cleaned out to bottom. Ran tubing to total depth with Dowell abrasive jet tool on bottom and cut 3 holes in casing at 6602', 3 holes at 6588', 3 holes at 6578'. Circulated hole clean and pulled tubing and sand water fractured with 50,000 gals. water and 50,000 lbs. sand. Opened the well and flowed back water. Well cleaned up and flowed 5,368 MCFPD on Pitot tube test. Ran 2' tubing to 6600'. Shut the well in for 7 day pressure test, after which another open flow test will be taken.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **A. Eastern Development Company of Delaware**

Address **P. O. Box 427**  
**Artesia, New Mexico**

By **[Signature]**  
Title **Vice President**