


Form 7-5229
(Rev. 10-17)



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan
Lease No. S.F. 078397
Unit Marshall #4

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF <u>Surface</u> <u>X</u>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Marshall #4

June 11, 1956

Well No. 5 is located 1690 ft. from 104 line and 1190 ft. from E line of sec. 15

R4/4-S4/4 Section 15 27E 94 N. 12. 3. 1.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

South Platte San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6253 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded: 6:30 P.M. June 8, 1956
Run 7 Joints (133') 2-3/8" OD Casing - set at 133'
Cemented with 150 lbs. reg. cement with 2% calcium chloride,
circulated.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Marshall Oil Company

Address Box 426

Farlington, New Mexico

By P. E. Cosper

Title District Foreman